



PRODUCT CHANGE NOTICE

1. TITLE MANUFACTURER DATASHEET CORRECTION COBHAM UT8ERXM32 Table 2 Signal and Pin description		2. DOCUMENT NUMBER SPO-2021-PCN-0002	
		3. DATE (Year, Month, Date) 2021, 07, 14	
4. MANUFACTURER NAME AND ADDRESS CAES 4350 CENTENNIAL BOULEVARD COLORADO SPRINGS, COLORADO 80907-3486		5. MANUFACTURER POINT OF CONTACT NAME Mike Leslie	
		6. MANUFACTURER POINT OF CONTACT TELEPHONE 719 594-8148	
		7. MANUFACTURER POINT OF CONTACT EMAIL mike.leslie@caes.com	
8. CAGE CODE 65342	9. EFFECTIVE DATE ALL	10. PRODUCT IDENTIFICATION CODE QS11 QS12	11. BASE PART UT8ER4M32M/S
12. BLANK		13. SMD NUMBER 5962-10204	14. DEVICE TYPE DESIGNATOR ALL
		15. RHA LEVELS ALL	16. QML LEVEL ALL
		17. NON QML LEVEL ALL	18. GIDEP GB4-C-21-0002

19. PRODUCT CHANGE

This ADEPT is provided as notification that corrections to Cobham UT8ERxM32 datasheet, page 5, Table 2. Device Option: Signal and Pin Description are needed and in process.

Table 2 Device Option: Signal and Pin Description pinout was found to have errors for device option column UT8ER4M32M and UT8ER4M32S only. Pin 45 and 46 were listed as NC but should be E7# and E5# respectively.

The datasheet is being updated to reflect the following in table 2

Pkg Pin#	UT8ER1M32M (Master) Signal Name	UT8ER1M32S (Slave) Signal Name	UT8ER2M32M (Master) Signal Name	UT8ER2M32S (Slave) Signal Name	UT8ER4M32M (Master) Signal Name	UT8ER4M32S (Slave) Signal Name	Device Pin Description
45	NC	NC	NC	NC	E7#	E7#	Control Input
46	NC	NC	NC	NC	E5#	E5#	Control Input

20. DISPOSITIONARY RECOMMENDATION:	CHECK & <input type="checkbox"/> USE AS IS	CONTACT <input type="checkbox"/> MANUFACTURER	REMOVE & <input type="checkbox"/> REPLACE	CORRECT & <input type="checkbox"/> USE AS SPECIFIED
---	---	--	--	--